


## WIRING INSTRUCTIONS


# MI CT 01 00023

Series Issue Page WIRING INSTRUCTIONS NSX 12 March 2009 1 / 1



### STEP 1/

STRIP CABLE TO DIMENSIONS SHOWN ABOVE.



#### STEP 2/

SLIDE CLAMP NUT, RING GLAND, SEAL AND BRAID CLAMP OVER THE CABLE.

COMB BRAID UNTIL ALL STRANDS ARE STRAIGHT; CUT BRAID TO DIMENSION SHOWN.



#### STEP 3/

FOLD BACK BRAID OVER BRAID CLAMP. STRIP AND TRIM INNER CONDUCTOR AT DIMENSION SHOWN.

.256 (6,50) .236 (6,00)



#### STEP 4/

PLACE CENTER CONTACT OVER INNER CONDUCTOR UNTIL. STOPS AGAINST DIELECTRIC. SOLDER CENTER CONTACT.



INTRODUCE CENTER CONTACT / ASSEMBLY INTO OUTER CONTACT. OUTER CONTACT SLIDE DEAL AND RING GLAND INTO OUTER CONTACT SLIDE CLAMP NUT IN PLACE AND TIGHTEN WITH. 45 TO 55 INCH.POUND (52 TO 63 cm.daN) TORQUE

CREATION				
NAME: VALGRESY				
<b>DATE</b> : 12 March 2009				
APPR. : BROCHET	ISSUE	REVISIONS	NAME	APPROVED