




STRAIGHT PLUG CRIMP TYPE CABLE 3.6/50S





Technical Data Sheet

STRAIGHT PLUG CRIMP TYPE CABLE 3.6/50S

PAGE 2/3	ISSUE 28-01-25A	SERIES TNC	PART NUMBER R143088111
-----------------	---------------------------	------------	-------------------------------

PACKAGING

Standard	Unit	Other	
1	Contact us	Contact us	

ELECTRICAL CHARACTERISTICS

50 Impedance Ω Frequency 0-6 GHz **VSWR** 12 0,000 x F(GHz) Maxi √F(GHz) dB Maxi Insertion loss 0.06 RF leakage 57* - F(GHz)) dB Maxi - (Voltage rating 500 Veff Maxi Dielectric withstanding voltage 1500 Veff mini Insulation resistance 5000 $M\Omega$ mini

MECHANICAL CHARACTERISTICS

Center contact retention

 Axial force - Mating End
 27
 N mini

 Axial force - Opposite end
 27
 N mini

 Torque
 NA
 N.cm mini

Recommended torque

 Mating
 265
 N.cm

 Panel nut
 NA
 N.cm

 Clamp nut
 370
 N.cm

 A/F clamp nut
 8,000
 mm

Mating life 500 Cycles mini Nominal Weight 22,200 g

(Add +15% for max

weight)

ENVIRONMENTAL

Operating temperature
Hermetic seal
Panel leakage

-65/+165

NA
Atm.cm3/s

NA

SPECIFICATION

ASNE0461-F05

CABLE ASSEMBLY

Stripping		b	С	d	е	f
mm	9,700	9,500	24,200	0,000	0,000	0,000

Assembly instruction:

Recommended cable(s)

EN 4604-003 (WZ)

Characteristics indicated on this data sheet are those that can be achieved with the highest performance cable. Intrinsic limitations of the cable may diminish the performance of the assembly

Cable retention

- pull off 110 N mini - torque NA N.cm

TOOLING

Part Number	Description	Other
282291	CRIMPING TOOL M2252/1-01.	2x4 (pos 8)
282997	LOCATOR	Red position
R282223000	CRIMPING TOOL HEX 1.73-5.41-6.48	5.41
R282246000	CRIMPING DIES M22520/5-05.	5.41
R282293000	CRIMPING TOOL: M22520/5-01	


OTHER CHARACTERISTICS

* Up to 3 GHz



Technical Data Sheet


STRAIGHT PLUG CRIMP TYPE CABLE 3.6/50S



1

Slide onto the cable the heatshrink sleeve and the ferrule

Strip the cable and cut the foil under the braid. Optionally, to facilitate the stripping of the inner cable, the length "a" could be stripped after crimping of the ferrule.




2

Slide the clamp nut onto the crimp sleeve.

Slide sub-assembly under the braid.

Slide ferrule over the braid against clamp nut.(In direction F) Crimp the ferrule with crimping tool + dies



3

The dielectric must be in the same plane as the face of the crimp sleeve. Cut the dielectric flush to crimp sleeve if it exceeds. Clean the dielectric side.


Mount insulator against crimp sleeve.

Insulator

4

Slide the center contact onto the cable inner conductor against insulator.

Crimp the center contact with the crimping tool and the positioner.



5

Screw sub-assembly into the connector body. (recommended coupling see the connector TDS) Slide heatshrink sleeve over ferrule and put in the place as below

